UNITED STATES DISTRICT COURT FOR THE NORTHERN DISTRICT OF ILLINOIS EASTERN DIVISION

VALLEY AIR SERVICE, INC., Au Illinois Corporation,)
Plaintiff,) Case No.: 06 C 0782
v.) Judge Manning
SOUTHAIRE, INC.,) Magistrate Judge Mason
A Tennessee Corporation,	Ś
Defendant.)

PLAINTIFF'S INITIAL DISCLOSURE PURSUANT TO FEDERAL RULES OF CIVIL PROCEDURE RULE 26

NOW COMES Plaintiff VALLEY AIR SERVICE, INC., an Illinois corporation, by and through its attorneys, Schnell, Bazos, Freeman, Kramer, Schuster & Vanek, and hereby makes the following Initial Disclosures pursuant to Federal Rules of Civil Procedure Rule 26:

- 1. The following individuals are likely to have discoverable information that the disclosing party may use to support its claims or defenses:
 - a) Maureen Cosyns, Valley Air; 416 Renner Dr. Elgin, IL 60123
 - b)Stephen Cosyns, Valley Air; 416 Renner Dr. Elgin, IL 60123
 - c)Edward Brunner, Paul (pilot for Ed-flew N17WC often) Southaire; 8245 Tournament
 - Dr. Memphis, TN 38125
 - d)Central Flying Service, Inc. employees-Bill Woods, Valerie Holeman, John Shirley,
 - Mike Englert and Timothy Snipes; others; 1501 Bond St. Little Rock, AR72202.
 - e)J. A. Aero, Inc.; Bruce Rebacini (sp) other employees, 3N060 Powis Rd., West

Chicago, IL 60185

Page 1 of 3

- f) Rickie Boyd, Advantage Aircraft Sales, Inc.-Ricky Boyd, 1273 Broadway, South Fulton, TN 38257.
- g) SWAT-allegedly repaired fuel leaks for Central Flying but Plaintiff confirmed with SWAT that it did not work on plane;
- 2. The following documents, data compilations, and tangible things that are in the disclosing party's possession, custody, or control may be used to support said party's claims or defenses:
 - a) Aircraft sale and purchase agreement-Plaintiff exhibit A to complaint
 - b)Executed aircraft acceptance certificate exhibit B and attachment
 - c)Central Flying Service work orders and detail of all work done on subject airplane before delivery-possession of Southaire and Central Flying Service;
 - d)Cessna Cescom-10 reports
 - e)J. A. Aero, Inc. work repair orders and records after Plaintiff took possession of subject airplane;
- 3. The following is a computation of damages claimed by the disclosing party, with the supporting documentation on which said computation is based being available for inspection and copying pursuant to Federal Rule of Civil Procedure Rule 34:

Answer: \$225,582.27 approximately; investigation continues; see attached Excel summary sheet.

Respectfully Submitted,

VALLEY AIR SERVICE, INC., an Illinois corporation

y. ______

SCHNELL, BAZOS, FREEMAN, KRAMER, SCHUSTER & VANEK

CERTIFICATE OF MAILING

Under penalties as provided by law pursuant to Code of Federal Procedure the undersigned certifies that she did deposit a copy of the foregoing PLAINTIFF'S DISCLOSURE STATEMENT PURSUANT TO FEDERAL RULES OF CIVIL PROCEDURE RULE 26, in a U.S. Post Office Box in Elgin, Kane County, Illinois, by email and enclosed in an envelope, properly and securely sealed with U.S. Postage fully prepared thereon, and plainly addressed to the person listed below on the 20th day of April, 2006 at approximately 3:00 p.m.

Stryon

Mark D. Johnson Victor J. Pioli Johnson & Bell, Ltd. 33 W. Monroe St. Ste. 2700 Chicago, IL 60603

Joseph M. Lamonaca, Esq. 127 Commons Court Chadds Ford, PA 19317

Robert Kramer, Esq., ARDC #01523570 Andrew E. Kolb, Esq., ARDC #6270096 Nicholas J. Johnson, #6283168 Schnell, Bazos, Freeman, Kramer, Schuster & Vanek Attorneys for Plaintiff 1250 Larkin Ave. Suite 100 Elgin, Illinois 60123 (847) 742-8800

UNITED STATES DISTRICT COURT FOR THE NORTHERN DISTRICT OF ILLINOIS EASTERN DIVISION

VALLEY AIR SERVICE, INC.,)	
Plaintiff, v.) .)	No. 06 cv 00782
SOUTHAIRE, INC., et al.,)	Judge Blanche M. Manning Mag. Judge Michael T. Mason
Defendants.	.)	

PLAINTIFF VALLEY AIR SERVICE, INC.'S ANSWERS TO DEFENDANT, CENTRAL FLYING SERVICE, INC.'S FIRST SET OF INTERROGATORIES

Plaintiff, Valley Air Service, Inc. ("Valley Air") answers the following Interrogatories propounded by Defendant, Central Flying Service, Inc.

INTERROGATORIES

INTERROGATORY NO. 1: Please state the date on which you first contacted Southaire about the possible purchase of the Aircraft.

ANSWER: Objection. The interrogatory assumes unproven facts (i.e. that Valley Air "first contacted Southaire"). Without waiving said objection, Valley Air answers as follows: Valley Air contacted a third-party aircraft broker, sometime prior to July 15, 2005 with respect to the purchase of a different airplane, and was informed of the availability of the Aircraft on or about July 15, 2005 by the third-party aircraft broker. Valley Air was contacted by Southaire, Inc. sometime thereafter.

<u>INTERROGATORY NO. 2</u>: Please state the date on which you first contacted CFS about your possible purchase of the Aircraft from Southaire.

ANSWER: Presently unknown.

<u>INTERROGATORY NO. 3</u>: Please state the date on which you first traveled to CFS's facilities in Little Rock, Arkansas to view the Aircraft.

EXHIBIT

2

ANSWER: On or about July 29, 2005.

<u>INTERROGATORY NO. 4</u>: Please state every other date on which you traveled to CFS's facilities in Little Rock, Arkansas.

ANSWER: September 16, 2005, October 7, 2005, and October 11, 2005.

INTERROGATORY NO. 5: Please state the name of every officer, agent and/or employee of Valley Air who communicated in any form with CFS and/or Southaire. If any of these individuals are no longer employed by Valley Air, please provide his or her last known address and phone number.

ANSWER: Stephen Cosyns, Maureen Cosyns. Michael Patrick, 1521 Brittania Way, Roselle, IL 60172-401, (630) 980-4621.

<u>INTERROGATORY NO. 6</u>: Please state the name of every officer, agent and/or employee of Southaire with whom you communicated in any form.

ANSWER: Ed Brunner, Paul (last name unknown).

INTERROGATORY NO. 7: Please state the name of every officer, agent and/or employee of CFS with whom you communicated in any form.

ANSWER: Valerie Holeman, Bill Woods, John Shirley, Mike Englert, Timothy Snipes.

INTERROGATORY NO. 8: Please state the name of every employee of Valley Air who performed any work or maintenance on the Aircraft. If any of these individuals are no longer employed by Valley Air, please provide his or her last known address and phone number.

ANSWER: No "work," as defined in the definitions section accompanying these interrogatories and limited to "activities to be performed on the Aircraft as set forth in the Agreement," was performed by any Valley Air employee. David Spencer performed maintenance on the Aircraft.

INTERROGATORY NO. 9: Please state the name, address and phone number of every individual or entity with whom you contracted to perform any work or maintenance on the Aircraft.

ANSWER: "Work," as defined in the definitions section accompanying these interrogatories and limited to "activities to be performed on the Aircraft as set forth in the Agreement," was

performed by Central Flying Service, Inc. and Southaire, Inc. Further answering, the following entities performed maintenance on the Aircraft.

J.A. Air Center Lionel Fritz, Director of Maintenance 3N060 Powis Road West Chicago, IL 60185 630-584-3200

Jet Aviation Chicago-Midway Maintenance Division 6150 South Laramie Avenue Chicago, IL 60638 773-581-5111

Cessna Orlando 4134 Bear Road Orlando, FL 32827 407-859-1245

Pratt & Whitney
Dave McIntyre
43W752 US Highway 30
Sugar Grove, IL 60554
815-341-2194

Central Flying Service, Inc. 1501 Bond Street Little Rock, Arkansas 72202

Southaire, Inc. 8245 Tournament Dr. Memphis Tennessee 38125

<u>INTERROGATORY NO. 10</u>: Please state the name, address and phone number of every person whom you may call as a witness at the trial of this matter.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 22.

INTERROGATORY NO. 11: Please state the name, business address, home address and home and business telephone numbers of each person you may call as a witness at the trial of this matter, whether lay or expert. For each expert, who may be called at trial or who is used for consultation and is not expected to be called as a witness but whose work product either (1) forms a basis, in whole or in part, of the opinions of an expert who may be called as a witness, or (2) has been reviewed by any person you may call as a witness at trial, please state the subject matter on which each expert is expected to testify; the mental impressions and opinions held by

each expert, and the facts known and other information furnished to the expert which relate to or form the basis of the expert's mental impressions and opinions.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 23.

INTERROGATORY NO. 12: Please provide an itemization of the damages you have allegedly suffered and please state the total amount of damages you have allegedly suffered.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 24.

INTERROGATORY NO. 13: Please state the basis for your contention in paragraph 80 of your first amended complaint that Valley Air was an intended third party beneficiary of an agreement between CFS and Southaire.

ANSWER: Objection. This interrogatory calls for a legal conclusion, and seeks to invade privileged attorney work product.

INTERROGATORY NO. 14: Please specify all dates on which the Aircraft was flown after it was delivered to you, and identify the pilots who flew the Aircraft on each of those dates. Attach a copy of the current pilot's license and medical certificate for the pilots named herein.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 2.

<u>INTERROGATORY NO. 15</u>: Please identify the person who performed the Pre-Purchase Inspection for Plaintiff.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 5.

INTERROGATORY NO. 16: Please identify the person who performed the Part 1-V Inspection on the Aircraft.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 7.

INTERROGATORY NO. 17: Please identify the date and location of each of Plaintiff's inspections of the Aircraft.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 8.

INTERROGATORY NO. 18: As to all aircraft discrepancies listed in paragraph 74 of your first amended complaint, please describe with specificity the exact discrepancy, when it was first noticed, and where it was recorded as a maintenance item/discrepancy.

ANSWER:

- a. Aircraft leaks fuel item noted by Central and logged as a RFQ Item # 5024. On information and belief, Central has further information responsive to this interrogatory.

 Documentation is attached to Valley Air's Answer to Southaire Interrogatory 9(a).
- b. Faulty window seal noted on October 7, 2005. Central logged as Maintenance Discrepancy Item # 5002. On information and belief, Central has further information responsive to this interrogatory. Documentation is attached to Valley Air's Answer to Southaire Interrogatory 9(b).
- c. Improper elevator trim Central logged as RFQ Item # 5033 on or before August 2, 2005. On information and belief, Central has further information responsive to this interrogatory. Documentation is attached to Valley Air's Answer to Southaire Interrogatory 9(c).
 - d. Paint, including around main cabin door.
 - e. Improper application of registration.
- f. Damaged throttles The throttles were improperly rigged as discovered by J.A. Air Center. The aircraft was in the custody of J.A. Air Center to correct a discrepancy for stiff and misaligned throttles as logged in the maintenance logbook on November 3, 2005. J.A. Air Center discovered the throttles out of rig between November 3, 2005 and November 14, 2005, the date the item was cleared, reflected on J.A. Air Center WO# 14517, Item 101.
- Inoperative communication equipment Pilot's push-to-talk (PTT) Switch was reported inoperative on October 7, 2005. On information and belief, Central has further information responsive to this interrogatory. See documentation provided in Valley Air's Answer to Southaire Interrogatory 17.
- h. Malfunctioning co-pilot gyro Right side HSI precessing 1.5 degrees per minute discovered on October 7, 2005. On information and belief, Central has further information responsive to this interrogatory. See documentation provided in Valley Air's Answer to Southaire Interrogatory 17.

- i. De-ice light item complained of in error. Upon further investigation, Valley Air finds that this item was satisfactorily addressed and is no longer part of Plaintiff's First Amended Complaint.
- j. MAPCO logged as defective on October 28, 2005 in the maintenance logbook. Documentation is attached to Valley Air's Answer to Southaire Interrogatory 9(k).
- k. Galley drain noted as defective by Central prior to October 11, 2005. On information and belief, Central has further information responsive to this interrogatory.
- m. Industry Standards see a-k above in response to this item. Documentation is attached to Valley Air's Answer to Southaire Interrogatories.
- n. Specifications of the Agreement see a-k above in response to this item.

 Documentation is attached to Valley Air's Answer to Southaire Interrogatories.
- o. Safe Flight see a-k above in response to this item. Documentation is attached to Valley Air's Answer to Southaire Interrogatories.
- p. Suitable for safe flight see a-k above in response to this item. Documentation is attached to Valley Air's Answer to Southaire Interrogatories.
- *q.* Safety investigations see a-k above in response to this item. Documentation is attached to Valley Air's Answer to Southaire Interrogatories.

<u>INTERROGATORY NO. 19</u>: As to each item identified in response to the preceding interrogatory, please state whether the aircraft was ever flown by any pilot of Valley Air, at any time after delivery with the discrepancies not corrected, and to the extent the discrepancies were corrected please state when, where, and by whom they were corrected and further attach the corresponding maintenance record for the correction:

ANSWER: Valley Air never operated the aircraft with any known discrepancy in contravention of safety or regulatory standard. When items were discovered in flight which necessitated repair prior to subsequent flights the Aircraft was removed from service and the items serviced. Cosmetic items, such as interior color choices have yet to be corrected and the Aircraft performance not affected. Items, including the fuel leak, were found to be within operation limitations, although not within accepted maintenance standards.

- a. Aircraft leaks fuel item not repaired. Documentation attached in Valley Air Answers to Southaire Interrogatories.
- b. Faulty window seal Central reported to Valley Air that the item was repaired. Item reoccurred on November 3, 2005 and was repaired by J.A. Air Center prior to next flight. See WO# 14517 dated November 14, 2005. Documentation attached in Valley Air Answers to Southaire Interrogatories.
- c. Improper trim Aircraft repaired prior to any flight subsequent to discovery of problem. See Maintenance Clearing Action dated October 21, 2005. Documentation attached in Valley Air Answers to Southaire Interrogatories.
 - d. Paint, including around main cabin door non-grounding item.
 - e. Improper application of registration numbers non-grounding item.
- f. Malfunctioning throttles item allegedly repaired by Central prior to Valley Air taking possession of the Aircraft. Upon discovery on initial flight, November 3, 2005, the aircraft was grounded for repair by J.A. Air Center. See J.A. Air Center WO# 14517, Item 101. Documentation attached in Valley Air Answers to Southaire Interrogatories.
- Malfunctioning communication equipment—item repaired and Aircraft returned to service on October 21, 2005. See WO# 06469 dated October 21, 2005. Documentation attached in Valley Air Answers to Southaire Interrogatories.
- h. Malfunctioning co-pilot gyro item repaired and Aircraft returned to service on April 4, 2005. Documentation attached in Valley Air Answers to Southaire Interrogatories.
- i. De-ice light item complained of in error. Upon further investigation, Valley Air finds that this item was satisfactorily addressed and is no longer part of Plaintiff's First Amended Complaint.
- j. MAPCO Item reported by Central as working, however, was discovered inoperative on and repaired and returned to service on October 28, 2005. Documentation attached in Valley Air Answers to Southaire Interrogatories.

- k. Galley drain non-grounding item.
- m. Industry Standards see a-k above in response to this item. Documentation attached in Valley Air Answers to Southaire Interrogatories.
- n. Specifications of the Agreement see a-k above in response to this item.

 Documentation attached in Valley Air Answers to Southaire Interrogatories.
- o. Safe Flight see a-k above in response to this item. Documentation attached in Valley Air Answers to Southaire Interrogatories.
- p. Suitable for safe flight see a-k above in response to this item. Documentation attached in Valley Air Answers to Southaire Interrogatories.
- q. Safety investigations see a-k above in response to this item. Documentation attached in Valley Air Answers to Southaire Interrogatories.

INTERROGATORY NO. 20: On October 28, 2005, was the subject aircraft flown from Palwaukee Airport, (KPWK) to Salt Lake City Airport (KSLC), and then back to KPWK on the same day? If the answer is yes, please state who was the Pilot in Command, and attach a copy of his or her FAA Pilot Certificate, and further describe in detail all discrepancies found during this flight for the subject aircraft.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 18.

INTERROGATORY NO. 21: Please provide the name and FSDO or address of each and every FAA Official that has inspected and/or been involved with the subject aircraft since the delivery date from defendants to Valley Air.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 19.

<u>INTERROGATORY NO. 22</u>: Please provide the name and FSDO of Valley Air's FAA Primary Operations Inspector.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 20.

<u>INTERROGATORY NO. 23</u>: Is the subject aircraft used by Valley Air for Charter under Part 135?

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 21.

INTERROGATORY NO. 24: Please identify any individual that took any photographs, movies or videotapes of the aircraft since it has been in the possession of Valley Air. Provide the persons, name, address and phone number.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 26.

INTERROGATORY NO. 25: Please provide the name address and telephone number of each and every passenger that has been on the subject aircraft since its delivery to Plaintiff by defendant.

ANSWER: See Valley Air's answer to Southaire, Inc.'s Interrogatory 27.

Respectfully submitted,

VALLEY AIR SERVICE, INC.

By:

One of Its Attorneys

Alan L. Farkas
Jeffrey D. Waltuck
Madsen, Farkas & Powen, LLC
20 South Clark Street
Suite 1050
Chicago, Illinois 60603
Phone: (312) 379-3444

CERTIFICATE OF SERVICE

The undersigned attorney states on oath that he caused a copy of the foregoing PLAINTIFF VALLEY AIR SERVICE, INC.'S ANSWERS TO DEFENDANT, CENTRAL FLYING SERVICE, INC.'S FIRST SET OF INTERROGATORIES to be served by depositing a true and correct copy thereof in a sealed envelope, first class postage prepaid in an official depository of the U.S. Mail located at 20 South Clark Street, Chicago, Illinois 60603 on the 20th day of February, 2007, upon the following individuals:

Mark D. Johnson Victor J. Pioli Johnson & Bell, Ltd. 33 W. Monroe St. Ste. 2700 Chicago, IL 60603 w/ out attachments

Joseph M. Lamonaca Joseph Michael Lamonaca, PC 127 Commons Court Chadds Ford, PA 19317

Chad W. Main Christopher E. Kentra Meckler Bulger & Tilson LLP 123 N. Wacker Dr. Ste. 1800 Chicago, IL 60606 w/ out attachments

Charles T. Coleman
Paul D. Morris
Wright, Lindsey & Jennings LLP
200 W. Capitol Ste. 2300
Little Rock, AR 72201

Jeffrey Waltuck

ATTESTATION

I AFFIRM UNDER THE PAINS AND PENALTIES FOR PERJURY THAT I HAVE READ PLAINTIFF VALLEY AIR SERVICE, INC.'S ANSWERS TO DEFENDANT SOUTHAIRE'S FIRST SET OF INTERROGATORIES AND I FIND THAT THEY ARE TRUE, ACCURATE, AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

VALLEY AIR SERVICE, INC.

Ву:

Print Name: Stophon Cosins
Title: Anisi Ost

UNITED STATES DISTRICT COURT FOR THE NORTHERN DISTRICT OF ILLINOIS EASTERN DIVISION

VALLEY AIR SERVICE, INC.,)	
Plaintiff, v.	÷)))	No. 06 cv 00782
SOUTHAIRE, INC., et al.,)	Judge Blanche M. Manning Mag. Judge Michael T. Mason
Defendants.		•)	

PLAINTIFF, VALLEY AIR SERVICE, INC.'S RESPONSE TO DEFENDANT, CENTRAL FLYING SERVICE, INC.'S REQUEST FOR PRODUCTION OF DOCUMENTS

Plaintiff, Valley Air Service, Inc. ("Valley Air") responds to Defendant Central Flying Service, Inc's Request for Production of Documents as follows:

REQUEST FOR PRODUCTION OF DOCUMENTS

<u>REQUEST FOR PRODUCTION NO. 1</u>: Please produce all written communications between Valley Air and CFS.

Response: Attached.

<u>REQUEST FOR PRODUCTION NO. 2</u>: Please produce all written communications between Valley Air and Southaire.

Response: Attached.

REQUEST FOR PRODUCTION NO. 3: Please produce all documents related to any work or maintenance performed on the Aircraft by Valley Air or a third party related to the alleged deficiencies in the Aircraft which form the basis of this lawsuit.

Response: No "work," as defined in the definitions section accompanying these interrogatories and limited to "activities to be performed on the Aircraft as set forth in the Agreement," was "performed on the Aircraft by Valley Air or a third party related to the alleged

EXHIBIT

3

deficiencies in the Aircraft which form the basis of this lawsuit." Maintenance documents are available for viewing and reproduction upon reasonable notice.

REQUEST FOR PRODUCTION NO. 4: Please produce all exhibits Valley Air may introduce at the trial of this matter.

Response: Valley Air has not yet identified and/or created its trial exhibits. Valley Air may utilize any document previously identified or provided by itself, Central Flying Service, Inc., Southaire, Inc., Cessna Aircraft Corp., Pratt & Whitney, SWAT, Skandia, or any other aircraft component manufacturer, supplier or tester, or any other heretofore unidentified third-party. Further, Valley Air may exhibit any document created by any expert it may hereafter retain. Exhibits will be provided in accordance with appropriate Court order. Valley Air reserves the right to supplement its response to this interrogatory.

REQUEST FOR PRODUCTION NO. 5: For each person identified as an expert witness, please produce a copy of:

- (a) His or her resume;
- (b) History of testimony;
- (c) All accounting records showing the amounts charged by the experts and the amounts paid by the plaintiffs or their attorneys;
- (d) Each written document (including, but not limited to, correspondence, photographs, reports, and bills) that concerns his or her testimony about, or investigation of, this case; and
- (e) Each document that the expert has reviewed in formulating opinions for the case.

Response: There are no documents responsive to this request at this time. Valley Air reserves the right to amend and supplement its response to this request in accordance with Court order. Further, Valley Air reserves any and all objections to this request until such time as it has identified its expert(s).

REQUEST FOR PRODUCTION NO. 6: Please produce all documents, including but not limited receipts and invoices, which tend to support the amount of damages Valley Air has allegedly suffered.

Response: The documents are available for viewing and reproduction upon reasonable notice.

<u>REQUEST FOR PRODUCTION NO. 7</u>: Please produce all documents which support your contention that Valley Air was an intended third party beneficiary of an agreement between CFS and Southaire.

Response: Objection. This interrogatory calls for a legal conclusion, and seeks to invade privileged attorney work product.

<u>REQUEST FOR PRODUCTION NO. 8</u>: Please produce the agreement referenced in paragraph 80 (subpart f) in which Valley Air was allegedly named and otherwise referred to.

Response: Objection. The interrogatory assumes unproven facts (i.e. that there existed a singular agreement). Further objecting, this interrogatory calls for a legal conclusion, and seeks to invade privileged attorney work product. Further objecting the request is unduly burdensome. The documents are believed to be in the possession of Central Flying Service, Inc. and Southaire, Inc.

<u>REQUEST FOR PRODUCTION NO. 9</u>: Please produce all Pilot Certificates, Pilot Log Book entries, Flight Discrepancy Reports, Maintenance Reports, and flight Plans relating to all dates and persons listed in your response to Interrogatory No. 2.

Response: There are no documents responsive to this request as it relates to Interrogatory No. 2.

REQUEST FOR PRODUCTION NO. 10: Please produce all FAA Flight Records, Data Tapes, and Flight Plans relating to all dates and persons listed in your response to Interrogatory No. 14.

Response: See Valley Air's Response to Southaire, Inc's Document Request # 3.

<u>REQUEST FOR PRODUCTION NO. 11</u>: For each and every flight of the Aircraft after the date of delivery, please provide a copy of the FAA Pilot Certificate and Medical of the pilot in command.

Response: See Valley Air's Response to Southaire, Inc's Document Request # 5.

<u>REQUEST FOR PRODUCTION NO. 12</u>: For each and every flight of the Aircraft after the date of delivery to Valley Air by Defendants, please provide every discrepancy report and the associated maintenance reports.

Response: See Valley Air's Response to Southaire, Inc's Document Request # 6.

REQUEST FOR PRODUCTION NO. 13: Please provide a copy of all Valley Air FAA Certifications and manuals including but not limited to Part 135 Certificates, DOT Economic Authority Certificates, and Valley Air FAA Approved Operations Manuals.

Response: See Valley Air's Response to Southaire, Inc's Document Request #7.

REQUEST FOR PRODUCTION NO. 14: Provide a copy of all Valley Air Pilot Training Certificates including FAR Part 61.58, 135.293 and 135.298 certificates.

Response: See Valley Air's Response to Southaire, Inc's Document Request #8.

REQUEST FOR PRODUCTION NO. 15: Please provide copies of all documents relating to the FAA Part 91 inspection of the subject aircraft, and the results of said inspection.

Response: See Valley Air's Response to Southaire, Inc's Document Request # 11.

REQUEST FOR PRODUCTION NO. 16: Please provide copies of any and all documents relating to the Phase I-V inspection, and the results of said inspection.

Response: See Valley Air's Response to Southaire, Inc's Document Request # 12.

<u>REQUEST FOR PRODUCTION NO. 17</u>: Please provide any photographs, videos, and movies in your possession of the Aircraft.

Response: See Valley Air's Response to Southaire, Inc's Document Request # 14.

REQUEST FOR PRODUCTION NO. 18: Please provide any and all documents containing any reference to any of the deficiencies identified by Plaintiff in the complaint.

Response: See Valley Air's Response to Southaire, Inc's Document Request # 15.

Respectfully submitted,

VALLEY AIR SERVICE, INC.

By:

One of its Attorneys

Alan L. Farkas
Jeffrey D. Waltuck
Madsen, Farkas & Powen, LLC
20 South Clark Street
Suite 1050
Chicago, Illinois 60603
Phone: (312) 379-3444

CERTIFICATE OF SERVICE

The undersigned attorney states on oath that he caused a copy of the foregoing PLAINTIFF, VALLEY AIR SERVICE, INC.'S RESPONSE TO DEFENDANT, CENTRAL FLYING SERVICE, INC.'S REQUEST FOR PRODUCTION OF DOCUMENTS to be served by depositing a true and correct copy thereof in a sealed envelope, first class postage prepaid in an official depository of the U.S. Mail located at 50 South Clark Street, Chicago, Illinois 60603 on the 20th day of February, 2007, upon the following individuals:

Mark D. Johnson Victor J. Pioli Johnson & Bell, Ltd. 33 W. Monroe St. Ste. 2700 Chicago, IL 60603 w/ out attachments

Joseph M. Lamonaca Joseph Michael Lamonaca, PC 127 Commons Court Chadds Ford, PA 19317

Chad W. Main
Christopher E. Kentra
Meckler Bulger & Tilson LLP
123 N. Wacker Dr. Ste. 1800
Chicago, IL 60606
w/ out attachments

Charles T. Coleman
Paul D. Morris
Wright, Lindsey & Jennings LLP
200 W. Capitol Ste. 2300
Little Rock, AR 72201

Jeffrey D Walted

VALLEY AIR SERVICES REPORT CITATION II S/N 550-0478

March 14, 2008

PREPARED BY:

RICK MILBURN

MILBURN & ASSOCIATES, INC. 15 WEDGEWOOD DR. GALENA, ILLINOIS 61036 815-777-1600

The following report has been prepared as a service to the law firm Madsen, Farkas, & Powen, LLC. 20 S Clark St. Suite 1050, Chicago, IL. 60603.

BASIS OF OPINION:


The opinions in this report are solely those of Milburn & Associates, Inc. These opinions are based on the review of the depositions presented to me in this case as well as various exhibits also presented to me. Additionally I have used information available in the Citation 550 Maintenance Manual, on the internet, the Aircraft Blue Book, various trade publications, present & past experience and industry knowledge. The opinions in this report are related to the purchase of the aircraft by Southaire, Inc., services performed by Central Flying Service, Inc. ("CFS"), the sale to Valley Air Service, Inc. ("VAS"), and values of the aircraft before, during, and after the sale. These opinions will be stated to a reasonable degree of certainty under the standards generally followed and accepted by aviation professionals and/or supported by the Manufacturer's Maintenance Manual and case documents.

QUALIFICATIONS:

Rick Milburn has been in the Corporate and General Aviation Industry for thirty six (36) years. His experience level covers aircraft from single engine piston through larger jets. He began his career as an FAA Certified Avionics Technician. Other positions have included Avionic Manager, General Manager, Aircraft Sales Manager, Vice President, and Co-Owner at three of the largest full service/sales facilities in Illinois.

- Capitol Aviation/Garrett Aviation, Springfield, Illinois
- · Walston Aviation (now West Star Aviation), Alton, Illinois
- JA Air Center/JA Aero, Inc., West Chicago, Illinois

Presently Milburn is the owner of Milburn & Associates, Inc. an aviation consulting company and AvSales, Inc a registered aircraft dealer and broker. Both companies are Illinois corporations with a focus on light aircraft to mid-sized jets. Milburn has either directly sold or supervised the sale of nearly 1000 aircraft in the last twenty eight years including Citation aircraft (Like the subject aircraft).



Milburn has been directly involved with the sale and acquisitions (including pre-purchase evaluations) of a number of Citation aircraft.

In doing so he has worked closely with maintenance personnel both as a customer and as a manager of a maintenance/service facility. Having had this first hand experience, he has gained a well rounded knowledge of FAA maintenance requirements and learned to use maintenance experts to advise in maintenance situations, as well as an appreciation of how these issues are typically dealt with in the industry. At the time of this writing AvSales, Inc. has one Citation V under brokerage contract and is monitoring its progress through a major scope of maintenance including Phase 1-5 inspections, double hot section inspections and gear replacement.

Prior to his civilian career Milburn served in the U.S. Air Force for four years and graduated from Aircraft Electronic School. Milburn was awarded the Air Force Commendation Medal for his efforts in Southeast Asia.

Before lowing the Air Force Milburn majored in Rusiness Administration at Illinois.

Before joining the Air Force Milburn majored in Business Administration at Illinois State University. Milburn has also attended several non-credited business and technical courses.

INDUSTRY RECOGNITION:

Case 1:06-cv-00782

- Top 40 Young Aviation Managers FBO Magazine
- Managed two Top Five Avionics Shops Professional Pilot Magazine
- Man of The Year 2004 Chicago Area Business Aviation Association(CABAA)
- · Board of Advisors several major Avionics Manufacturers

PROFESSIONAL AFFILIATIONS:

- NBAA National Business Aviation Association
- CABAA Chicago Area Business Aviation Association Past President/Director
- CABAA Educational Foundation President

PRIOR LEGAL DEPOSITIONS/TESTIMONY (last four years)

• 2007 Condo Association Suit against a contractor. State of Mississippi Waverly Place Condo Association v. Tabor Construction, Parker Roberson Construction, Sto Corporation, and Sto of Louisiana – gave deposition

EXPERT WITNESS COMPENSATION

Milburn & Associates is being compensated at a rate of \$125.00 per hour.

3.

VALUEY AIR SERVICE

CASE OPINIONS

Throughout this report there are references to Mr. Brunner and Southaire, Inc. For clarification, when one is referenced they are meant to be one in the same, Brunner meaning Southaire and Southaire meaning Brunner. The same holds true for Mr. Englert and CFS, Englert meaning CFS and CFS meaning Englert.

PURCHASE BY SOUTHAIRE:

After reviewing the depositions of Mr. Brunner (May 29, 2007), Mr. Winegardner (Dec. 4, 2007), and exhibits #56, 57 & 60, I find the transaction to purchase by Southaire unusual and not to industry standards, to say the least. This may have little to do with the (Valley) case but I feel that it somewhat sets the tone of the whole transaction. I find it very unusual and not to normal industry standards that Brunner would act as a broker for AvTran, LLC to purchase an aircraft (550-0478) in the amount of \$1,325,000 and in the same day Southaire, Inc. (Brunner's company) purchased it from AvTran, LLC for \$1,425,000. The purchase prices are addressed in this report (Aircraft Values) and are less concerning than the fact that Southaire/Brunner could have bought the aircraft directly from Forest Hills Corporation since he was the broker for the AvTran transaction. Brunner could have spent \$100,000 less than he ultimately paid. According to Brunner, AvTran, LLC financed it for Southaire, Inc. This may suggest there were some improprieties in this transaction(s). This series of transactions are not common or to industry procedures.

It would also be unusual for Southaire to pay a commission to Paul Eremea (Eremea Dec.4, 2007) after Southaire sold the aircraft when he was only involved in the Southaire purchase. I suppose that paying a commission to a person Mr. Winegardner considered "his pilot" might not seem ethical. It certainly would not be common in the industry to compensate an employee or assumed employee of the other party monetarily.

As discussed more fully below, Southaire's acquisition cost was below market value for this aircraft. All parties involved in the transaction were knowledgeable and sophisticated. Therefore, the price is strongly indicative of Southaire's knowledge that the aircraft was being sold in a distressed condition.

Based on Brunner representations of the aircraft and his relationship to the pilot that had been flying for the last several years, he should have been knowledgeable of the condition and history of the aircraft.

met v

SOUTHAIRE SALES/MARKETING:

Southaire placed the aircraft for resale as soon as they bought the aircraft and presented specifications that not only listed the equipment specifications of the aircraft but also the additional work that was contracted for with CFS. VAS reasonably relied on these specifications to be accurate and therefore found the aircraft to be suitable to replace the Citation that had been removed from their Charter operation as it was represented. An aircraft with fresh inspections, new paint, and interior could be put to work immediately and VAS would realize a reduced amount of downtime and lost revenue.

SERVICES BY CENTRAL FLYING SERVICE:

There are several depositions and exhibits referenced in regards to CFS's work on Citation II S/N 550-0478. I will note each by name and date or exhibit number when appropriate.

Brunner put the aircraft into maintenance as soon as he purchased the aircraft and advised CFS to do a cursory pre-purchase, and then a Phase 1-5 inspection. Once he had contracted with VAS, the Phase 1-5 was to become the VAS pre-purchase inspection, according to the sales contract between Southnire and Valley Air Service. This Phase 1-5 had already been requested by Brunner and was represented to the potential buyers (per specification sheet) and ultimately VAS as being done to the manufacturer's requirements (see sales contract). At that time CFS was performing the work per contract for VAS as well as Southaire. CFS contracted for other items with VAS, as well.

Brunner requested (exhibit #15) a records cheek and a phase 1-5 inspection under Part 91 (private operator not for hire). Even though Brunner requested this service, on the Aircraft Documentation Survey Request & Authorization (exhibit #3) he declined Time Limited items. Items which would determine current status of all components with mandatory time change requirements. An example of this is the Flap Gear Box (see Smith April 16, 2007) page 23 item 5-12. Mr. Dewayne Smith states that the customer fills out the survey sheet and decides what he/she wants CFS to check in the inspection, In this case Brunner did not check the Time Limited Items (items that have to be replaced or serviced at a certain time), therefore Smith said that CFS had no obligation to replace out the flap gear box that was due within days of the delivery. Mr. Smith in his deposition (April 16, 2007) states to following, "if your unwilling to pay the bill, I'm not held responsible for the airworthiness of your aircraft. So in other words, if he don't pay for it we don't provide the service". (Page 27 item 2) It is with a reasonable degree of certainty that I believe that the Time Limited items must be done. Chapter 4 of the Citation II Maintenance Manual says that "Replacement Time Limits (4-10-00) gives the life-limited components, that are TO BE REPLACED at a specified time. Neither Mr. Brunner nor Mr. Englert or Mr. Smith has the option to defer Time Limited items.

Under Part 91 the inspections called out by the Manufacturer's Maintenance Manuals have to be followed or the inspection cannot be signed off as "complete". The Phase 5 (complete Airframe inspection) in this case can't be signed off as complied with, even if noted that items had been deferred. The reason for this is CFS did not comply with the inspection requirements of the Manufacturer's Maintenance Manual or other specific manuals approved by the manufacturer. Therefore "Airworthiness" did not exist. I would defer to a Maintenance Expert to discuss this issue in any greater depth.

Mr. Brunner told Valley Air that he would deliver a "no excuses" aircraft. Valley Air reasonably understood this to mean that Southaire was not to spare any expense or defer any items that would come up during the inspection. Yet this was not the case.

If became common knowledge that the ultimate owner of the aircraft would be Valley Air Service, Inc. yet there is no evidence that anyone at CFS advised that the inspections that were requested by Southaire would not comply with the requirements of Part 135 (passengers for hire). They did not advise Valley Air that Service Bulletins required for Part 135 were not being complied with either. Valley Air, on the other hand, could rightfully think that the aircraft was getting a Phase 1-5 that would meet his requirements and needs. Based upon my experience and industry knowledge, the maintenance facilities have a duty to inform the potential owner/operator of possible requirements in addition to what work was being done. I believe this is standard in the industry. An example would also be the L/H Aileron Balance weight that will have to be replaced the next time the weight has to be adjusted (Exhibit 22 CFS (0102)). This is part of the unfortunate history that should have been revealed as part of the pre-purchase inspection because it significantly affects the value and marketability of the aircraft and would be material to any prospective purchaser's decision to proceed with a purchase of the aircraft. This shoddy workmanship could also alert a prospective purchaser to expect additional problems.

It appears that CFS is under the impression that they can decide or the customer can decide what should be repaired or not during the course of the inspection. Under Part 91, the Manufacturer's Maintenance Manual will describe how items must be serviced or repaired. If, for instance, the deice light is inoperative, it is therefore unairworthy because it is part of an inspection requirement. Mike Engleri (April 16, 2007) on page 100 item 15 says that he would have to get the customers approval to make a repair that is clearly part of the Phase inspection. However, if there is no repair or replacement made per the manual then it is unairworthy and the inspection is not complete.

CFS has demonstrated a lax approach to determining what is airworthy and lack of attention to detail. Dewayne Smith (April 16, 2007) describes missed items as "over sights." The Complaint points out several items, such as the Mapco, the de-ice light, cabin drawers, galley drain, glare shield extensions, and improperly installed door lock, that are prime examples of carelessness, and are all items that are part of the inspection process.

....

During the process of stripping the aircraft for paint, CFS notes that there were "major dents" that had been filled by parties unknown. The dents were described as being all along the tops of the wings and fuselage. My industry knowledge and experience (purchased twelve aircraft with hail damage) with this type of dent would normally indicate hail damage.

In the depositions, the dents were described as major which would also indicate hail damage. It would be a normal course of action in the aviation industry to have the aircraft surfaces determined airworthy and not risk safety of flight. Secondly if the damage was repaired, a log book entry would be made reflecting the repair of the hail damage. In this case there was no log entry for the repair (filling) of the damaged surfaces. It is a standard in the industry that physical damage to any aircraft and the method of its repair can cloud the value of the aircraft for many years. (See Aircraft Values Section). Once again, this is a condition that should have been revealed to VAS as part of the unfortunate history and should have been revealed as part of the pre-purchase inspection. This item significantly affects the value and marketability of the aircraft and would be material to any prospective purchaser's decision to proceed with a purchase of the aircraft.

As for the paint work itself at CFS, Mr. John Shirley testified as follows when asked about doing a better job with the paint. (Shirley Dec.3, 2007 page 22). "In order to prevent issues like I see in front of me from taking place, you would have to go back to a total bare skin and do all the buildups from that point forward." Mr. Shirley also said "That is pretty much just an industry standard. I mean it's atypical, you know, you don't go remove all filler on an aircraft when you're repainting it."

I have learned through experience in the industry that if the filler is not removed when the aircraft is stripped, the stripper will penetrate the filler and two things may happen.

- · The filler may soften/crack and fall out
- The stripper can penetrate to the airframe surface and cause corrosion

AIRCRAFT PURCHASE BY VALLEY AIR SERVICE:

Valley Air Service (VAS) hought Citation II S/N 550-0478 in October, 2005 from Southaire, Inc. for a purchase price of \$1,913,667.00 (Exhibit #40). An aircraft sales/purchase agreement commonly used in the industry contained the terms and condition of the sale as well as exhibits. (Exhibit#15) The sale was conducted under the Laws of Illinois and the title of the aircraft was transfer to Valley Air Service, Inc via a Warranty Bill of Sale. The sales agreement and the terms and conditions were typical of that normally used in the aviation industry. The closing was handled through an Escrow account at AIC Title in Oklahoma City.

VAS, as is normal in the aviation industry, would have relied heavily on the representations of the seller contained in the initial solicitation and in the sales contract.

The sales contract provides:

Section 5(b): The Aircraft has a valid FAA Certificate of Airworthiness and is in airworthy condition with all systems in normal operating condition, per manufacturer's maintenance and operating manuals and specifications.

Section 5(c); "All log books" (ii) for the period prior to the date the Aircraft was owned by Seller, true, complete, and correct to the best of the Sellers knowledge." (Cescom reports were, in fact, missing).

Section 5(d): The Aircraft has had all required inspections to the date of Closing and all Airworthiness Directives and Mandatory Service Bulletins have been complied with. Section 5(h): "No damage history is reflected in the Aircraft's records from the time of the first delivery by the manufacturer, except as specifically noted in Exhibit "B"." Section 6.2(a): The Aircraft and the Aircraft documents have already been delivered to Central Flying Service, Little Rock, Arkansas ("the Inspection Facility") for the purpose of enabling the Inspection Facility to conduct (at seller's expense) an inspection ("Pre-Purchase Inspection") of the Aircraft. (The pre-purchase inspection requested by Brunner was insufficient by industry standards).

Each of the above items has been addressed in this report and should be construed as having not been complied with.

VAS also relied on CFS to perform the maintenance to industry standards and to the level that the FAA has entrusted them with in their Repair Station License. VAS relied on CFS to know the FAA regulations and to perform the work to the requirements necessary to return the aircraft to service in the condition as described by the seller in the sales agreement

VAS relied on CFS to provide a complete and indisputable maintenance history after their work was complete. An aircraft with uncertain records, questionable engine and airframe times and incomplete inspections will undoubtedly be of less value and take longer to sell than an equal aircraft with reliable records and maintenance history.

The aircraft was accepted in Little Rock, Arkansas after a test/acceptance flight. VAS requested a second flight, but this request was denied. It was not an unreasonable request, especially since VAS offered to pay for the flight. The denial of the second flight unreasonably forced VAS's hand to depart with the aircraft as is.

..Q..

VAS relied on the representations by Mr. Englert that all the issues were addressed before the acceptance. Mr. Englert had a responsibility to provide an honest reporting of the pre-purchase inspection.

It is also normal that the aircraft might not be returned to the maintenance facility that is responsible due to the long distance and expense involved in returning to that facility. In those cases the seller would make arrangements with the buyer to have the work accomplished at another facility unless it is warranted by another party. If the work is warranted by a third party, then the seller who was paying their bill would normally negotiated with the maintenance facility so the buyer can have the work done somewhere else. In this case VAS had no confidence in CFS's ability to repair the aircraft.

AIRCRAFT VALUES:

The values placed on an aircraft by an appraiser for a bank is based strictly on the specifications, times, condition, etc. that is presented to him/her and is assumed correct. The difference between an appraisal and the actual market value can differ drastically. One of Milburn & Associates, Inc. associates (Aviation Management Consult, Inc.) is a Certified Member of the American Society of Appraisers. The two companies work together on projects for this very reason.

To reestablish an estimated retail value of the aircraft at the time of the sale is difficult at this time. With the use of the Summer 2005 Blue Book as a basis for an average aircraft plus or minus the options or deficits of the aircraft in question, will give us a very good estimate of the retail value, and this is the standard method used in the industry.

2005 Retail Average Book Value \$1,725,000.00 (Time of Sale to VAS)

Recent RVSM Compliance \$50,000 - \$100,000 (Reversed Vertical Separation Minimums)

Recent Hot Sections (Engines) \$60,000-\$80,000

Fresh Phase 1-5 Inspections

\$29,500.00

Fresh Paint & Interior

\$100,000,00

Retail Price Range Summer 2005 \$1,964,500.00 - \$2,034,500

2003 Wholesale Average Value \$1,500,000.00 (Time of Purchase by Southaire)

Resent RVSM Compliance \$50,000 - \$100,000

Recent Hot Sections (Engines)\$60,000 - \$80,000

Needed Phase 1-5 (as quoted) (\$61,

(\$61,400.00)

Needed Paint & Interior

(\$29.500.00)

Needed Paint & Interior

(\$100,000.00)

Wholesale Price Range 2005

\$1,419,100,00 - \$1,489,100.00

....

If VAS had known all the facts of the condition of the aircraft, that CFS had not complied with the Manufacturer's Maintenance Manual, that there was undisclosed hail damage, that there was no thorough Pre-Purchase Evaluation, that there were missing Cescom Reports, and questions about the actual times on the aircraft and engines, then VAS would have reevaluated the purchase price. Based on the items listed above the Actual Purchase Price should have been in the range of \$1,675,000.00. This number is arrived at as follows:

Actual Selling Price	\$1,925,000.00
Hail Damage	(200,000.00) minimum
Cescom/Log Reconstruction	(10,000.00)
Reconstruct actual Times	(10,000.00)
Re-verify Phase 5 and S/B	(30,000.00)
Actual Value at Time of Sale	\$1,675,000.00

Based on these figures, at the time of the sale the selling price fell into the Retail selling range, but the actual value would have been less if the facts been known. The price that Southaire bought the aircraft for was closer to a Forced Liquidation Value.

The major variable to the Retail value would be the hidden hail damage that was never revealed in the logs. As stated before, physical damage leaves a lasting cloud on the value of the aircraft forever. Based on the experience of owning aircraft with hail damage (for resale), and my experience in the industry, it is my opinion that the depreciation for hail damage would be ten (10%) to fifteen (15%) percent. At retail that could have varied the value by \$200,000.00 to \$300,000.00. The other variables are listed above. What are not listed are the many discrepancies that were found at the inspection, such as the Ailcron weight that will have to be replaced.

Rather than purchase the aircraft at a reduced price, however, it would be far more likely and reasonable for a purchaser in the position of VAS, who is purchasing the aircraft for actual use, to decline the purchase and find an aircraft with a more reliable history.

REPORT SUMMARY:

- The aircraft was purchased by AvTran, LLC and Southaire, Inc in a transaction that is uncommon to what is normal in the industry.
- Southaire paid a \$100,000 premium by involving AvTran
- A commission was paid to the pilot of the past owner, which is not normally done
 in the industry. He was an employee or assumed employee of the previous owner.
- There was never a pre-purchase inspection done for AvTran as required in their purchase agreement and an incomplete evaluation for VAS at Brunner's request.
- Brunner did only a cursory inspection of the aircraft. He did much less than normally expected in the industry. (see sales contract)

- Brunner requested that none of the Time Limit Items be checked during the Phase inspections.
- CFS employees honored Brunner's request on Time Limit items and testified that this is permitted under Part 91 rules.
- Part 91 inspections must be done per the Manufacturer's Maintenance Manual and Chapter 4 clearly states that Time Limit Item are TO BE REPLACED at a specific time. There is no allowance for deferral.
- CFS employees failed to disclose to Valley Air Service (VAS) that there were service bulletins that would be required for Part 135 that were not being addressed in the inspections. This is the common practice within the industry.
- More than one employee of CFS testified that they allow customers to elect what inspections are done under Part 91, which is contrary to the guidance of the Manufacturer's Maintenance Manual.
- CFS credits the numerous smaller discrepancies left undone to "oversights"
- After stripping the aircraft for paint it was discovered that the tops of the wings and fuselage was covered with "major dents" and had been filled with bondo filler. The major dents were most likely unrecorded hail damage.
- Hail damage should be recorded in the log books after repair and return to service.
- CFS employees testified that the filler used on the aircraft was not removed after the aircraft was stripped.
- Chemical stripper will destroy the filler and cause it to pop out. The stripper will
 also penetrate to the aircraft skin and cause corrosion.
- VAS bought the aircraft under Illinois Law, per the terms of the sales agreement, and title was transferred via Warranty Bill of Sale.
- VAS reasonably and necessarily relied on the representations of the seller and CFS as to the actual condition of the aircraft.
- The aircraft was delivered to VAS in Little Rock, Arkansas with known discrepancies which both parties agreed to as not being corrected.
- The seller should have assisted VAS in having the repairs done without returning to CFS. This is common practice within the industry.
- At the time of purchase the price VAS paid was within the Retail price range.
 This price is higher than its actual worth when considering the damage history and maintenance performed.
- The prices that Southaire and certainly AvTran paid for the aircraft were at below wholesale market and closer to a Forced Liquidation Value.
- Physical damage to an aircraft diminishes the value permanently.

-11-

- The undisclosed hail damage would have a depreciation effect on the aircraft of ten percent (10%) to fifteen percent (15%) or \$200,000.00 to \$300,000.00
- This aircraft was bought of Commercial use and downtime for additional maintenance is very very costly due to the lost revenue at the time of maintenance.

Dia W Milyana

President

J A Air Center Work Order 14 3N060 Powis Road Du Page Airport Invoice Date 2/28 West Chicago, IL. 60185 Page 630/584-3200 630/584-7883 Fax Number FAA Approved Repair Station NF2R029L Customer Id. 724010 VALLEY AIR SERVICE Registration # N17WC 416 RENNER DRIVE Make..... CESSNA ELGIN IL 60123-6903 Serial Number. 550-0478 Aircraft Time. 6,504 Date In..... 2/28/06 Date Completed 2/28/06 Billing Summary Inside Habor Charges 445.0 Materials And Accessories 3.6 Misc. Other & Freight 15.3 Tax At 0675 PAY THIS AMOUNT

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above aircraft for purposes of testing. Inspection or delivery at my risk. An express mechanic's lien is acknowledged on above 464.2 aircraft to secure the amount of repairs thereto. You will not be held responsible for loss or damage to aircraft or articles left in aircraft in case of fire, theft, accident, freezing, or any other cause beyond your control. ENDORSEMENTS ENTERED IN LOG BOOK Progressive Preliminary Insp..._ Operations 1-2-3-4... Hidden Damage Insp..____ 50 Hour.... Progressive Insp.... 100 Hour..... Final Insp..... Work Performed By..... Employee No Date 3-98-06
Preliminary Inspection. Employee No Date 3-98-06
Hidden Damage Inspection. Employee No Date 3-98-06 Final Inspection..... Employee No. Date 3-18-00
Approved By..... Employee No. Date 3-28-00 The Aircraft and/or components identified above were repaired and inspected in accordance with current regulations of the Federal Aviation Agency and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under Work Order No 14766 Signed **EXHIBIT** BRUCE P. REBECHINI

"WE SERVICE WHAT WE SELL"

Work Order Invoice Date

2/28, Page

Registration # N 17WC

Flat Rate & Inside Labor Charges

Item Discrepancy Amount 600 AD2006-04-10 MIS-WIRE OF FIRE EXTINGUISHING BOTTLES-COMPLIED WITH AD2006-04-10 AS PER TABLE 1 OF THE AD BY COMPLIANCE OF SB550-26-05 AND INSTALLING SERVICE KIT AS PER STEPS 1 THRU 11. NO FURTHER ACTION IS REQUIRED. Labor Hours .5 @ 89.00 /Hr 44.50 625 COMPLY WITH SB550-26-05 TO PREVENT MIS-WIRE OF FIRE EXTINGUISHING BOTTLES-COMPLIED WITH SB550-26-05 BY INSTALLING SERVICE KIT AS PER PAGES 1 THRU 11. NO FURTHER ACTION IS REQUIRED. Labor Hours @ 89.00 /Hr 400.50


Work Order Invoice Date

14' 2/28, Page

Registration # N 17WC

Material And Accessories

Part#	<u>Description</u>	Qty	Price	Amount
MS25171-1S	NIPPLE	2	1.81	3.62
Total Materials And	Accessories			3.62



Work Order Invoice Date


2/28

Page

Registration # N 17WC

Miscellaneous Charges

Ven# Services	Repairs		Other	Freigl
MISC EPA		,	15.35	
Total Outside Services	.00		15.35	. C



J A Air Center 3N060 Powis Road Du Page Airport West Chicago, IL. 60185 630/584-3200 630/584-7883 Fax Number FAA Approved Repair Station NF2R029L Customer Id. 724010

ELGIN ·

Work Order

Invoice Date

11/] Page

VALLEY AIR SERVICE 416 RENNER DRIVE

Registration # N17WC Make.... CESSNA

Model....

550

Serial Number.

550-0478 Aircraft Time. 5,384

Date In..... 11/09/05 Date Completed 11/14/05

Billing Summary Inside Labor Charges Materials And Accessories Misc. Other & Freight Tax At .0675

IL 60123-6903

4,180. 157. 156.

10.

PAY THIS AMOUNT

4,504.

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above aircraft for purposes of testing. Inspection or delivery at my risk. An express mechanic's lien is acknowledged on above aircraft to secure the amount of repairs thereto. You will not be held responsible for loss or damage to aircraft or articles left in aircraft in case of fire, theft, accident, freezing, or any other cause beyond your control.

ENDORSEMENTS ENTERED IN LOG BOOK Progressive Preliminary Insp.... Hidden Damage Insp. 50 Hour.

Progressive Insp. 100 Hour.

Final Insp. Annual. _____Operations 1-2-3-4... Final Insp....

Work Performed By..... Employee No Ambreliminary Inspection. Employee No Employee No Ambreliminary Inspection. Employee No Emp _ Date _ Date __ _ Date_ Date /1/14/.5 Date /1//y/.5 The Aircraft and/or components identified above were repaired and inspected in accordance with current regulations of the Federal Aviation Agency and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under

Work Order No 14517 Signed Online

Date 11/14/05

DONALD K. MORGAN

Tel 1451
...olce Date 11/14/0
Page
Registration # N 17WC


Flat Rate & Inside Labor Charges

Item	n Discrepancy	Amount
100	PILOTS SIDE WINDOW DEVELOPS FROST BETWEEN PANELS- REMOVED COCKPIT SEATS, OVERHEAD PANELS, CHART BOXES & BOTH LH TOP AND BOTTOM SIDEWALLS TO ACCESS THE DEFOG SYSTEM. FOUND THE SUPPLY HOSE INTACT AND SECURE. WINDOW DEFOG ONLY OPERATES WHEN FOOTWARMER IS SELECTED OPEN. NO DEFECTS NOTED. REINSTALLED INTERIOR AS REQUIRED.	
10 1	Labor Hours 13.2 @ 88.00 /Hr THROTTLES NOT ALIGNED-	1,161.60
	INSPECTED & RERIGGED BOTH ENGINE CONTROLS IN ACCORDANCE WITH THE CESSNA 550 MAINTENANCE MANUAL. OPERATIONAL CHECKED AND RIGGED AS NECESSARY. ON RUNUP AND RESAFETIED AS NECESSARY.	
102	Labor Hours 17.8 @ 88.00 /Hr LH FOUL WINDOW LEAKS AIR IN FLIGHT- ADJUSTED FOUL WEATHER WINDOW HINGES AS REQUIRED.	1,566.40
20 0	Labor Hours 2.6 @ 88.00 /Hr	228.80
	INSPECTED AILERON SYSTEM, REMOVED FLOOR IN AFT CABIN AND LOCKED BELLCRANK. REMOVED COCKPIT FLOOR TO INSPECT PULLEYS AND CABLES. CHECKED TRAVELS AND FOUND TO BE IN SPECIFICATIONS AS PER CESSNA 550 MAINTENANCE MANUAL 27-11-00. REINSTALLED ALL PANELS AND CARPET. Labor Hours 5.0 @ 88.00 /Hr	
201	RIG AILERON TRIM SYSTEM- INSPECTED TRIM SYSTEM. FOUND TRAVELS OUT OF RIG. RIGGED ALLERON TRIM TRAVELS AS PER CESSNA 550 MAINTENANCE MANUAL CH	440.00
500	27-11-00. OPERATIONAL CHECK SATISFACTORY. Labor Hours 3.5 @ 88.00 /Hr CHECK GEAR DOOR WHEN RETRACTED, NOISE REPORTED DURING FLIGHT- JACKED AIRCRAFT AND CYCLED GEAR. FOUND NORMAL OPERATION	308.00
	OF GEAR. INSPECTED AND FOUND NO DEFECTS. COULD NOT DUPLICATE DISCREPANCY. RESERVICED HYDRAULIC RESERVOIR.	The state of the s
	Labor Hours 5.4 @ 88.00 /Hr	175 On

1451 ...voice Date 11/14/0 Page Registration # N 17WC

Material And Accessories

Part#	Description	Qty	Price	Amount
3008787 MS17825-4 SKYDROL	ROD END NUT 500B4 HYD FLUID PT	2 1 1	70.53 2.17 14.20	141.06 2.17 14.20
Total Materials And Acc	essories	,		157.43




Work Order Invoice Date

145] 11/14/(Page

Registration # N 17WC

Miscellaneous Charges

Ven# Services	Repairs	Other	Freight
SHIPPING HANDLING & INSURANCE MISC. EPA		130.89	25.70
Total Outside Services	.00	130.89	25.70



HISTORICAL

Aviation Fabricators, Inc. 805 North 4th St. Clinton MO 64735

invoice	12601	
Date	11/1/2005	
Rage	.1	

В	il	ľ	Γο:

Valley Air Services 416 Renner Drive Elgin IL 60123

Ship To:

Valley Air Services 416 Renner Drive Elgin IL 60123

								•
٠	SBurghase@rder.No.	CustomerID	Salespersor		payment gram			
ŕ	Ordered Shipped	VALLEYAIRS	SERVIC CSK	FEDEX P1	Credit Card	11/1/2005		
1 (11	1 0	80037-123 (OHC) 80037-123 (CORE)	Hot Liquid Container, PPI, Ol- Hot Liquid Container, PPI, Co	1C S/N 525 2	\$0.00 \$0.00	\$795.00 \$500.00	\$795.00 \$500.00
!	***					ŀ		
					-			,
	n, t							·
			•					
	ж. 1							
1	·			·				
	1							
· ·								

Includes Spigot Amex 3783 4689 6401 008 Exp 08-09

Silitatell - Section	\$1,295.00
	\$0:00
ījā vieta ir	\$0.00
Erejojne	\$33.15
Trade Discount	\$0.00
nogle - Leave	\$1,328,15

J A Air Center Work Order 3N060 Powis Road Du Page Airport Invoice Date 10/21 West Chicago, IL. 60185 Page 630/584-3200 630/584-7883 Fax Number FAA Approved Repair Station NF2R029L Customer Id. 724010 VALLEY AIR SERVICE Registration # N17WC 416 RENNER DRIVE Make.... CESSNA . Model.... 550 Serial Number. 550-0478 ELGIN IL 60123-6903 Aircraft Time. 5,372 Date In..... 10/20/05 Date Completed 10/21/05 Billing Summary Inside Labor Charges 1,070.1 Mise. Other & Freight 16.1 PAY THIS AMOUNT 1,086.2 I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above aircraft for purposes of testing. Inspection of delivery at my risk. An express mechanic's lien is acknowledged on above aircraft to secure the amount of repairs thereto. You will not be held responsible for loss or damage to aircraft or articles left in aircraft linease of fire, theft, accident, freezing, or any other cause beyond your control. ENDORSEMENTS ENTERED IN LOG BOOK Progressive Preliminary Insp... Operations 1-2-3-4.

Hidden Damage Insp... 50 Hour...

Progressive Insp... 100 Hour...

Final Insp... Annual... Work Performed By..... Employee No ρ_{∞} Date ρ_{∞} Date Preliminary Inspection. Employee No ρ_{∞} Date ρ_{∞} Date Hidden Damage Inspection. Employee No. ρ_{∞} Date ρ_{∞} Date Approved By.... Employee No. ρ_{∞} Date ρ_{∞} The Aircraft and/or components identified above were repaired and inspected in accordance with current regulations of the Federal Aviation Agency and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under Work Order No 14465 Date 10/21/05 Signed____ DONALD K. MORGAN

14

Work Order Invoice Date 144: 10/21/:

Page Registration # N 17WC

A, AP CARE

Flat Rate & Inside Labor Charges

Item	Discrepancy	Amount
200	ELEVATOR TRIM IMPROPERLY RIGGED- INSPECTED ELEVATOR TRIM SYSTEM CABLE TRAVEL AND INSTALLATION CORRECTED RIGGING OF THE TRIM TAB ACTUATOR, STOP BLOCKS AND	
	CABLE TENSION IN ACCORDANCE WITH THE 550 MAINTENANCE MANUAL CHAPTER 27-31-00. OPERATIONAL CHECK SATISFACTORY.	
201	Labor Hours 11.4 @ 87.00 /Hr	991.80
201	RUDDER TRIM OVER TRAVELS LEFT AND RIGHT- ADJUSTED RUDDER TRIM FOR 10 DEGREES OF TRAVEL LEFT AND RIGHT. SECURED STOP BLOCK IN ACCORDANCE WITH CESSNA 550	
	MAINTENANCE MANUAL 27-21-00. Labor Hours 9 @ 87.00 /Hr	78.30
	Labor Hours 9 @ 87.00 /Hr	
The second second		

No.206465 Cust. Phone No. 847-468-7473 Type AC Citation Aucran Reg. No TWC 10-21-05 SQ:OFC C. S. C. 22 Cust. Order No. Spec. Instr. Promised AMOUNT EPA/MISC. SUPPLIES TOTAL LABOR TOTAL PARTS SALES TAX FREIGHT TOTAL 724010 THANS PX Phone: (630) 584-3200 • Fax: (630) 584-7883 • Outside Illinois: (800) 323-5966 electrotic equipment, many delects which seem identical can be caused by any one of many part CALCircuts. It is therefore impossible to assume responsibility-ler any portion of your instrument (parts of circuits) on which we have not performed service at this time. We also (guarantee that your set will be restored to its normal performance upon completion of our repairs. However, in the event of dissalisfaction with set performance, we must be notified within 48 hours after ser is delivered or repaired. All work is performed by qualified technicians and all materials rised in the repair of this set and of just qualify and are guaranteed for a period of 90 days after the date of repair. Due to the complex nature of plepsingly 20H6. I HERBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS YOU AND YOUR MAY EARLOYEES MAY DPERAITE ABOVE ARGANG FOR PURPOSES OF TESTING. INSPECTION ON DELIVERY ATT PLASK.
AN EXPRESS MECHANICS THE IS ACKNOWLEDGED ON ABOVE ABOVE ABOVE TO SECURE THE ARGANG ATT PLENETO, YOU. WILL NOT BE HELD RESPONSIBLE FOR LOSS ON DAMAGE, TO ARGANG ON ARTICLES LEFT IN ABOVE IN CASE OF FIRE, THEFT, ACCIDENT, FREEZING, OR ANY OTHER CAUSE BEYOND YOUR CONTROL NO CHARGE FROOM WORK ORDER INSTRUCTIONS 3N060 Powis Road • West Chicago, IL 60185-1097 뿚 TITE CALLED WARRANTY JOLIET AVIONICS, INC. VOR - ILS - LOC. 0 SÉRVICE POTIÇÝ VALLEY AIR SERVICE CHARGE POWER SUPPLY 60123 416 RENNER DRIVE TOT CASH ELGIN, NAV-COM TOTAL LABOR HOURS AUTHÓRIZED BY OPER. NO. Serial No. Address Model **FERMS**: Make with current regulations of the 28-01 ir are on file at this Apend Dale Date Date I. A. AIR CENTER OLIET AVIONICS, INC. (eturn to service. Pertinent details TOTAL PARTS. EMPLOYEE NO. deral Aviation Agency and was den damage inspection; Aircraft and/or como sliminary inspection: ork performed by: irk Order No. al inspection: proved by:

J A Air Center Work Order 3N060 Powis Road Du Page Airport Invoice Date West Chicago, IL. 60185 630/584-3200 630/584-7883 Fax Number FAA Approved Repair Station NF2R029L Customer Id. 724010 VALLEY AIR SERVICE Registration # N17WC 416 RENNER DRIVE Make.... CESSNA Model..... 550 ELGIN IL 60123-6903 Serial Number. 550-0478 Aircraft Time. 5,384 Date In..... 10/24/05 Date Completed 11/04/05 Billing Summary Secretary Application Inside Labor Charges PAY THIS AMOUNT I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above abscraft for purposes of testing. Inspection or delivery at my risk. An express mechanic s lien is acknowledged on above aircraft to secure the amount of repairs thereto. You will not be held responsible for loss or damage to aircraft or articles be held responsible for loss of damage to different left in aircraft in case of fire, theft, accident, freezing, or any other cause beyond your control. ENDORSEMENTS ENTERED IN LOG BOOK Progressive 1-2-3-4.. Preliminary Insp..._ Operations 1-2-3-4. Hidden Damage Insp.._ 50 Hour..... Work Performed By..... Employee No &- Date ///u/s
Preliminary Inspection. Employee No & Date ///u/s
Hidden Damage Inspection. Employee No. A. Date ///u/s Final Inspection..... Employee No. 2~ Approved By..... Employee No. 2~ Date_ 08~ Date The Aircraft and/or components identified above were repaired and inspected in accordance with current regulations of the Federal Aviation Agency and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under Work Order No 14469// Date 11/04/05

11/0

Page

246.

246.

Signed

DONALD K. MORGAN

Work Order Invoice Date

11/04, Page

Registration # N 17WC

Flat Rate & Inside Labor Charges

Item Discrepancy

Amount


100

"N" NUMBER DECALS ON LEFT SIDE OF VERTICAL STAB. ARE PEELING OFF.

REMOVED DECALS FROM THE LEFT SIDE OF THE VERT. STAB. CLEANED AREA, ALIGNED AND INSTALLED CUSTOMER SUPLPLIED DECALS.

Labor Hours 2.8 @ 88.00 /Hr

246.40



WOODLAKI REFINISHING, INC.

Sandwich Airport 850 Piper Way Sandwich, Illinois 60548

Larry Baechi (815) 786-25% Fax (815) 786-900

Name Valley Air Service			Date				06	
Address			Invoice				**************************************	
Phone 1-847-468-7473 FAX-468-	 75^7(a		Registra	tion: N	O	165	00	**********
YEAR CHATION NO.		ERIAL		Mark Landson	, PAINT		TOTAL	TIME
I CESSINA CHATIONA	SUBLET WORK	'	PARTS MATER	AND	LA	BOR	REFI	VISH:
Ropair Filler around door	~		MATER	IACO				-
(Falling OFF) Prime and)							Cife (files es co
Paint white cayout and								
blend 3 stripes then	>	57	06	\$	65 C		#364	1/\
apply clearcoat	(100	10	ب و مهایها		TOCT	<u>1</u>
			<u> </u>		· · · · · · · · · · · · · · · · · · ·		***************************************	
Paint Laction kit per Doroth			758	86				
Paint Igallon kit PRC Desoto Matterhorn White			<u> زیمه ر</u>	ردن				listances :
Acri-glo stripe Colores		4	288	10	*	e e		
I quarticit each rolor	,	- 10	ار		** 			
		_						
Prep Materials		4	75					+
			<u>' - 2 </u>					-
	,							
p. 25.						+	1	+
	+		, ,	_				1
				_	·····	 		+
SUB TOTALS				Y III III				1
diake Refinishing, inc., does not warranty corrosion aint damage due to the environment.			<u> </u>			TAL	. 1~ 1 ~	+
ature	•			£		-	416) C
astimate is based on our inspection and does not cover additional parts or labor we ed after the work has been started. After the work has started, worn or damaged parts at on first inspection may be discovered. Network has started, worn or damaged parts	vhich may	_ be	P. STANSON TO POWER TO THE PORT		ALES	-	1	╁
nt on first inspection may be discovered. Naturally this estimate cannot cover such o prices subject to change without notice. This estimate is for immediate acceptance.	or D		SITION IRIT	A	ND TO	IAL IL	1162	0
	3			_	¥*	7.7		
	5.3	0-0	116					

					314107 - Invoige
GITY STATE ZIP	Len Andrews		ADDRES GITY-ST	ARC (28.47) (28.48) (2	PAIE
			and the second s		
				# 21/2	
	10 AC AND	the property of			
	215074 199 54602 7				
140 a		ett (25. g			

```
IN THE UNITED STATES DISTRICT COURT
 1
                FOR THE NORTHERN DISTRICT OF ILLINOIS
                           EASTERN DIVISION
 3
     VALLEY AIR SERVICE, INC.,
                                          ORIGINAL
 5
               Plaintiff,
                                     No. 06 CV 000782
 6
          vs.
 7
     SOUTHAIRE, INC., et al.,
               Defendants.
 8
 9
10
1.1
                    The deposition of STEPHEN COSYNS,
12
     called by the Defendants for examination, pursuant to
     Notice, and pursuant to the Rules of Civil Procedure for
13
     the United States District Courts pertaining to the
14
     taking of depositions, taken before Joanne M. Brogan, a
15
16
     Certified Shorthand Reporter and a Notary Public in and
     for the County of Cook and State of Illinois, at Suite
17
     1050, 20 South Clark Street, Chicago, Illinois, on
18
     Tuesday, May 29, 2007, at the hour of 4:50 o'clock p.m.
19
20
21
22
23
24
```

Page 173 Page 175 freon was low? 1 it. A It appeared to be low. 2 2 The agreed purchase price of the aircraft 3 3 Did you ever have that fixed? under the contract was \$1,925,000; is that correct? Q 4 We just recently did, yes. A That is what the contract stated. 5 Q When you say "recently," how recent is 5 Q When was your first conversation with 6 recently? 6 Mr. Brunner about reducing the purchase price? 7 A Two days ago. 7 A I don't think we ever asked him to reduce 8 O Okay. So between October 11th of '05 and the price. 9 two days ago, you've had the freon serviced once, 9 Q You never asked Mr. Brunner to reduce the 10 and that was two days ago? 10 purchase price of the aircraft from \$1,925,000? 11 A Repaired. 11 A Not that I'm aware of. He offered to give 12 Repaired? Q 12 us a reduced price. 13 Correct. 13 A Q And why did he do that? 14 Anything else on the aircraft that you 14 A. I think he honestly thought we weren't 15 blame on or you contribute to Central Flying Service 15 happy with the airplane itself. 16 or Mr. Brunner other than the items we just 16 Q And so did you agree to accept a reduction 17 discussed on Exhibit 35? 17 in the price of the aircraft? 18 A At this time I'm not aware of any. 18 A. I believe we did, 19 So Exhibit 35 are the items that you 19 Q So he offered to reduce the price of the 20 believe that Central Flying Service and Mr. Brunner 20 aircraft so that you would be happy with the 21 should be responsible for? 21 condition? 22 A I think the only thing that's not included 22 A You know, I don't recall what the exact 23 here is the downtime on the aircraft. 23 wording was on it. Maybe he was just being a nice 24 Q And what has the downtime on the aircraft 24 guy. Page 174 1 been? O And because you were not satisfied with the 2 A The downtime on the aircraft to complete aircraft, did you agree to pay a lesser price? 3 these items. 3 A I don't recall what the conversation was 4 Q And you're asking for Central Flying with Mr. Brunner at that time. 5 Service or Mr. Brunner to pay that to you? Q Well, did you accept his offer that you б A Yes. 6 would pay a lesser sale price, or did you say, "No, 7 Q And how much is that? I'm going to insist on paying the original agreed 7 8 A I don't know. purchase price of \$1,925,000"? 9 Q Have you made any attempt to calculate it? 9 A I think if somebody was being a nice guy 10 A No, I have not. 10 and offered me an airplane at a reduced price, I 11 So this lawsuit has been filed since think, as a businessman, it would be very good for 11 12 December of '05 and you have not made an attempt to 12 me to take it. 13 calculate that? 13 Q Okay. And does a good businessman 14 A I honestly don't know how you would 14 gratuitously reduce the purchase price of an 15 calculate it. 15 aircraft? 16 Q You think it would be pure speculation to 16 A I don't know. 17 17 Q Tell me about your conversation with A No, I think it would be a monthly average 18 Mr. Brunner when it was discussed that the price 18 19 of downtime on the airplane. 19 would be reduced? 20 Q You would just take an average? 20 A I don't recall. 21 21 A I would. Q Who was there? 22 O Because to do otherwise would be to 22 A I don't even recall that, 23 23 speculate? Was your wife there?

24

I don't know.

24

A I don't even know how you would speculate